Panaboard Software Revision History (12/July/2010) for UB-2815C / UB-2315C

(c) Panasonic System Networks Co., Ltd. 2006-2010

TWAIN Driver

Ver.	Changing issue(s) / Fixing problem(s)	Note
1.00	1. First Release	
1.10	Simplified Chinese and Japanese are supported.	
2.00	Changing help to HTML Help format. (Fix) The Panaboard Operation Panel does not appears correctly, when Click the File menu, then click Acquire Image in "Quick Image Navigator". Operation in Windows 7 32bit edition was confirmed.	Version for Windows Vista 32bit / Windows 7 32bit

USB Driver

•					
	Ver.	Changing issue(s) / Fixing problem(s)	Note		
	1.10	1. First Release			
	1.10	Simplified Chinese and Japanese are supported.			
	2.00	1.Changing for Windows Vista 32bit.2. Operation in Windows 7 32bit edition was confirmed.	Version for Windows Vista 32bit / Windows 7 32bit		

Board Image Capture

Ver.	Changing issue(s) / Fixing problem(s)	Note
3.00	1. First Release	
3.30	1.(Fix) Scan Image cannot be save to root folder.2. Operation in Windows 7 32bit edition was confirmed.	Version for Windows Vista 32bit / Windows 7 32bit

Driver Installer

Ver.	Changing issue(s) / Fixing problem(s)	Note
1.00	1. First Release	
2.00	1.Changing for Windows Vista 32bit.	Version for Windows Vista 32bit
2.01	1. (Fix) Drivers cannot be installed in Windows 2000.	
3.00	 Adding Board Image Capture. Operation in Windows 7 32bit edition was confirmed. 	Version for Windows 7 32bit

Notes of Software Installation on Windows Vista 32bit / Windows 7 32bit

- If the User Account Control window is displayed, select [Allow].
 If the Windows Security window is displayed, select [Install this driver software anyware]. When connecting the USB cable to your computer, the wizard window is not displayed in Windows Vista.

^{*} Microsoft, Windows and Windows Vista are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.