

***** Release Note for Firmware of KV-S4085C/S4065C *****

Copyright(C) 2013-2018, Panasonic System Networks Co., Ltd. All rights reserved.

=====
Version 1.40 -> 1.41

1. Change in production line of factory.

=====
Version 1.30 -> 1.40

Improved Function

1. Double Feed Detection is ignored when manual feeding is set by ADF select key on Control Panel.

=====
Version 1.20 -> 1.30

1. Added the function of Roller Cleaning/Replacement Notification control

=====
Version 1.11 -> 1.20

Fixed problems

1. Background color on startup is not recognized properly.
2. Problem in returning from sleep mode
3. Other problem

=====
Version 1.06 -> 1.11

1. Change in production line of factory

=====
Version 1.05 -> 1.06

Fixed problems

1. Problem about conveying documents
2. Other problem

=====
Version 1.04 -> 1.05

1. Change in production line of factory

=====
Version 1.03 -> 1.04

1. Improving recognition of control sheet and patch code

Fixed problems

1. Scanning start position is not proper.
2. Other problem

=====
Version 1.02 -> 1.03

Fixed problems

1. Problem of communication between device driver and firmware
2. Other problem