***	*** Release Note for TWAIN Driver *****
(c)	Panasonic Corporation 2010-2021
==: Vei	rsion 21.4.0.3 -> 21.4.0.4
1.	Update for a specific use for KV-S6120 series.
	rsion 21.3.0.3 -> 21.4.0.3
	Improve the message display when all documents are removed by Blank Page Removal or other function
==: Vei	rsion 21.2.0.1 -> 21.3.0.3
	To support the models below.  (V-S6120, KV-S6110, KV-S6100
	rsion 21.1.0.4 -> 21.2.0.1
	Update for improving security.  The permissions of the folder where executable files are installed are changed to Read-only for general users.
==: Vei	rsion 21.1.0.3 -> 21.1.0.4
1.	(Fix) Some minor bugs are fixed.
==: Vei	rsion 21.1.0.3 (updated 5/Aug/2020)
(Fi	 x)
1.	To fix the following [Device Driver] problem: [Device Driver] Version 20 (updated 5/Aug/2020)

In the installation after 1/Aug/2020, the scanner may be unrecognized due to the device driver

1. To fix the following problem:

installation failure.

Ve	Version 21.1.0.2 -> 21.1.0.3				
1.	(Fix) Scanning from flatbed may not finish correctly on the settings that "Document Number" printing with imprinter is ON and "Continuous Scanning Mode" is ON.				
	rsion 21.0.0.8 -> 21.1.0.2				
1.	The types selected in the default barcode settings has been changed.  An All Clear button and a Default button have been added to the Barcode Type Settings.				
	rsion 20.2.0.3 -> 21.0.0.8				
1.	To support the models below.  KV-S5078Y, KV-S5058,  KV-SL5100 MK2 / KV-SL5096 MK2 / KV-SL5095 MK2 / KV-SL5086 MK2 / KV-SL5085 MK2				
2.	Add the following functions.  - Faint Character Enhancement  - Output Document Number in Imprinter / Digital Imprinter				
Ve	rsion 20.1.0.0 -> 20.2.0.3				
	Add the below languages for Automatic-Orientation function.  [Slovenian]				
== Ve	rsion 20.0.0.3 -> 20.1.0.0				
1.	To support the models below.  KV-SL1077 MK2				
2.	To support the operating system.  Add "Windows Server 2019"				

Ve	Version 19.0.0.2 -> 20.0.0.3			
1.	Add the following functions.			
	- Support "ADF Simplex (Back)" for Paper Source.			
	- Support 50dpi for Resolution.			
	- Support 2/3 for Rate with Binary Image in MultiStream Resolution.			
	- Support 2/3 for Rate with Binary Image in Automatic Binary/Color Distinction Resolution.			
	- Support Deskew function on setting the document's scanning area.			
	- Add the following size in Paper Size.			
	Executive, B5(ISO), B6(ISO), C5, C6			
	- Add "Extension Mode" function in Digital Imprinter.			
	Enable to print characters other than upper/lowercase letters, numbers, and symbols or			
	to print character strings horizontally			
	- Change the default scan settings.			
	Dynamic Threshold: OFF -> ON			
	Automatic Image Orientation: OFF -> ON (for US region only)			
	- Add Simple Dialog.			
	rsion 18.6.0.1 -> 19.0.0.2			
1.	Add the below languages for Automatic-Orientation function.			
	[Czech], [Hungarian], [Romanian], [Croatian], [Greek], [Vietnamese], [Thai] - Note -			
	For using [Greek] and [Thai] languages on [Automatic-Orientation] function, it requires [OCR Engine] ver. 2.9 or later.			
2.	To support the models below.			
	KV-SL1066 MK2, KV-SL1056 MK2, KV-SL1055 MK2, KV-SL1036 MK2, KV-SL1035 MK2			
== Ve	rsion 18.5.0.1 -> 18.6.0.1			
1.	Update for a specific use.			
== Ve	rsion 18.3.0.0 -> 18.5.0.1			
1.	To add "Datamatrix" in the recognizable Barcode type.			

== Ve	======================================				
	To add "Aztec" in the recognizable Barcode type.				
== Ve	rsion 18.1.0.2 -> 18.2.0.6				
	To support the models below.  KV-N1058X, KV-N1028X, KV-N1058Y, KV-N1028Y  (Fix) Canceling for scanning from an application may not work correctly.				
	rsion 18.1.0.1 -> 18.1.0.2				
1.	To support the models below.  KV-S1037X  (Fix) For network models, TWAIN driver might not identify the scanner with USB when connecting with USB at first time to scanner which has already been connected via network.				
== Ve	======================================				
1.	To support the models below.  KV-S1058Y, KV-S1057C MK2, KV-S1028Y, KV-S1027C MK2,  KV-S1038, KV-S1037, KV-S1026C MK2				
== Ve	======================================				
1.	To support the models below.  KV-SL3066, KV-SL3056, KV-SL3055, KV-SL3036, KV-SL3035  To support the operating system.  Add "Windows Server 2016"				

3. Added a Data Printing character string (%XD) for Imprinter and Digital Imprinter function.

	Version 15.0.0.14 -> 16.1.0.1				
1. To su	pport the models below. S8150, KV-S8147, KV-S8130, KV-S8127, KV-S8120				
	Version 14.3.0.1 -> 15.0.0.14				
	pport the models below.				
KV-S	S7097, KV-S7077				
KV-S	SL5100, KV-SL5096, KV-SL5095, KV-SL5086, KV-SL5085				
2. [Incre	ement timing] is now added to the [digital imprinter] function.				
3. Adde	d a digital imprinter support models below.				
KV-	S7097, KV-S7077				
KV-	S7075C				
KV-	S5055C				
KV-	S5076H, KV-S5046H				
KV-	S4085CW, KV-S4085CL, KV-S4065CW, KV-S4065CL				
KV-	S1065C, KV-S1046C				
KV-	S1057C, KV-S1027C				
KV-	S1045C				
KV-	S1026C, KV-S1015C				
KV-	S1025C				
KV-	SL5100, KV-SL5096, KV-SL5095, KV-SL5086, KV-SL5085				
	SL1066, KV-SL1056, KV-SL1055, KV-SL1036, KV-SL1035				
4. To su	pport with bearer bar in barcode types of ITF.				
======					
Version 14.1.0.0 -> 14.3.0.1					
1. Add t	he below languages for Automatic-Orientation function.  h], [Dutch], [Danish], [Swedish], [Portuguese]				

Version 13.2.0.1 -> 14.1.0.0

-----

1. The installer includes following twain drivers

KV-S7075C,

KV-S5076H, KV-S5046H,

KV-S5055C,

KV-S4085CW, KV-S4085CL, KV-S4065CW, KV-S4065CL,

KV-S2087,

KV-S1065C, KV-S1046C,

KV-S1057C, KV-S1027C,

KV-SL1066, KV-SL1056, KV-SL1055, KV-SL1036, KV-SL1035,

KV-S1045C,

KV-S1026C, KV-S1015C,

KV-S1025C

2. To support the operating system.

Add "Windows 10 "

- 3. Change the default scan settings.
  - -Deskew: OFF -> ON
  - -Automatic Crop: OFF -> ON
- 4. Change the length of Margin 10mm to 14mm for KV-S1026C and KV-1015C.

The supported firmware is needed.

- 5. (Fix) The LoadLibrary error occurs in the specific application.
- 6. (Fix) The memory error occurs in the specific application for following model.

KV-S1057C, KV-1027C,

KV-SL1066, KV-SL1056, KV-SL1055, KV-SL1036, KV-SL1035

- 7. (Fix) The parameter error (ID:3026) occurs scanning with following settings at the same time.
  - ADF Duplex
  - Black and White (Dynamic Threshold)
  - Deskew
  - Smoothing

The related models are as follows:


KV-S7075C.

KV-S5055C,

KV-S1065C, KV-S1046C,

KV-S1025C,

KV-S1045C



Add "Windows XP 64bit", "Windows Server 2003", "Windows Server 2008", "Windows Server 2012"

## TWAIN Driver Version 10.0.1.0

-----

- 1. To add the scan page counter to scanning UI
- 2. Correction of errors in the French error message
- 3. To be able to start to scan again after jam error
- 4. Improvement of angular accuracy of Deskew

Windows refers to the Microsoft Windows operating system.

Windows XP refers to the Microsoft Windows XP operating system.

Windows 10 refers to the Microsoft Windows 10 operating system.

Windows Server 2003 refers to the Microsoft Windows Server 2003 operating system.

Windows Server 2008 refers to the Microsoft Windows Server 2008 operating system.

Windows Server 2012 refers to the Microsoft Windows Server 2012 operating system.

Windows Server 2016 refers to the Microsoft Windows Server 2016 operating system.

Windows Server 2019 refers to the Microsoft Windows Server 2019 operating system.

Microsoft, Windows, Windows Server and Windows Vista are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

Adobe, Photoshop, Acrobat are either registered trademarks or trademarks of Adobe Systems Incorporated in the United States and/or other countries.