

***** Release Note for User Utility *****

(c) Panasonic Corporation 2010-2021

=====

Version 8.3 -> 8.4

1. To support the model below.
KV-S6120, KV-S6110, KV-S6100.

=====

Version 8.2 -> 8.3

1. Added new communication error and changed some messages.
New: C40, C41, C64
Changed: C30, C74

=====

Version 8.1 -> 8.2

1. To support the model below.
KV-S5078Y, KV-S5058,
KV-SL5100 MK2 / KV-SL5096 MK2 / KV-SL5095 MK2 / KV-SL5086 MK2 / KV-SL5085 MK2
2. The [Error Log] button on the main dialog has been deleted, and the [System Log] button now supports saving the Zip file format, including other information.
Save the following information:
System Log
Error Log
Error logs stored on the scanner (Network scanner only)
Application and driver configuration files

=====

Version 8.0 -> 8.1

1. Added [Scanner Cleaning Video] button on main dialog.
This button launch Web browser for viewing "Scanner Cleaning Video".
It requires internet connection.

=====

Version 7.9 -> 8.0

-
2. To support the option below.

Roller exchange kit: KV-SS100, KV-SS101

Version 7.8 -> 7.9

-
1. To support the model below.

KV-SL1077 MK2

Version 7.7 -> 7.8

-
1. To support the operating system

Add "Windows Server 2019"

(Fix)

1. Fix some minor display problems in some languages.

Version 7.6 -> 7.7

-
1. To support the models below.

KV-SL1066 MK2, KV-SL1056 MK2, KV-SL1055 MK2, KV-SL1036 MK2, KV-SL1035 MK2

Version 7.5 -> 7.6

-
1. Added [Initialization settings] function at [Factory Reset].

Version 7.4 -> 7.5

-
1. To support the models below.

KV-N1058X, KV-N1028X, KV-N1058Y, KV-N1028Y

Version 7.3 -> 7.4

-
1. To support the models below.

KV-S1037X

(Fix)

1. Fix the display of Network Setting Tool in Russian language.
2. Even when two scanners are connected to the USB and network and the network is selected with [Scanner selection] of the user utility, USB connection will be made when the user utility is restarted.

=====
Version 7.1 -> 7.3

-
1. To support the models below.
KV-S1058Y, KV-S1057C MK2, KV-S1028Y, KV-S1027C MK2
KV-S1038, KV-S1037, KV-S1026C MK2

=====
Version 7.0 -> 7.1

-
1. To support the models below.
KV-SL3066, KV-SL3056, KV-SL3055, KV-SL3036, KV-SL3035
 2. To support the operating system
Add "Windows Server 2016"

=====
Version 6.16 -> 7.0

-
1. To support the models below.
KV-S8150, KV-S8147, KV-S8130, KV-S8127, KV-S8120
 2. Added [Volume] function to the buzzer settings dialog box.
The related models are as follows:
KV-S8150, KV-S8147, KV-S8130, KV-S8127, KV-S8120
 3. Added [Reduce Operation Noise When Feeding Documents] function to the maintenance settings dialog box.
The related models are as follows:
KV-S8150, KV-S8147, KV-S8130, KV-S8127, KV-S8120
 4. Added [LCD] function to the maintenance settings dialog box.
The related models are as follows:
KV-S8150, KV-S8147, KV-S8130, KV-S8127, KV-S8120
KV-S2087

=====
Version 6.14 -> 6.16

1. To support the models below.

KV-S7097, KV-S7077

KV-SL5100, KV-SL5096, KV-SL5095, KV-SL5086, KV-SL5085

2. Added [LCD contrast] function to the maintenance settings dialog box.

The related models are as follows:

KV-S2087

=====
Version 6.13 -> 6.14

1. To support the models below.

KV-S2087

2. To support the operating system

Add "Windows 10"

3. To support Scanning Glass Cleaning Notification function.

The supported firmware is needed.

4. To support the Adjusting the hopper position function for KV-S5076H / KV-5046H.

The supported firmware is needed.

=====
Version 6.12 -> 6.13

1. To support the models below.

KV-S1057C / KV-S1027C / KV-SL1066 / KV-SL1056 / KV-SL1055 / KV-SL1036 / KV-SL1035

=====
Version 6.11 -> 6.12

1. To support the models below.

KV-S2048C / KV-S2028C

=====
Version 6.10 -> 6.11

1. To support the models below.

KV-S5076H / KV-S5046H

2. The name of "Caution Setting" button is changed.

"Caution Setting" -> "Roller Maintenance"

=====

Version 6.8 -> 6.10

-
1. To support the models below.
KV-S1026C / KV-S1015C
 2. A button to access the download page is added.
 3. A button to save a log file for scanner is added.
 4. The part number of Roller Exchange Kit is added to the message for roller replacing.
 5. To support the operating system
Add "Windows XP 64bit", "Windows Server 2003", "Windows Server 2008", "Windows Server 2012"

=====
Version 6.6.0.13 -> 6.8.0.20

-
1. To support the models below.
KV-S1065C/46C
 2. Traditional Chinese is excepted.
 3. Korean is supported.
 4. The folder which outputs a log file is changed.
"High Speed Scanner" -> "Document Scanner"

=====
Version 6.6.0.12 -> 6.6.0.13

-
1. When using 'KV-S5055C', waiting sensor information is added in "Save Info" .

=====
Version 6.5-> 6.6

-
1. To support the models below.
KV-S5055C
 2. The help file format is changed from 'PDF' to 'HTML'.

=====
Version 6.4.0.12 -> 6.5.0.1

-
1. The life of New DFP (double feed prevention) roller is changed from 50,000 to 100,000 sheets and the counter is used in common with counter of paper feed roller as one counter.
And the caution message to replace the rollers is displayed at 100,000 sheets.

(Fix)

1. Some bugs are fixed

Windows refers to the Microsoft Windows operating system.

Windows XP refers to the Microsoft Windows XP operating system.

Windows Server 2003 refers to the Microsoft Windows Server 2003 operating system.

Windows Server 2008 refers to the Microsoft Windows Server 2008 operating system.

Windows Server 2012 refers to the Microsoft Windows Server 2012 operating system.

Windows Server 2016 refers to the Microsoft Windows Server 2016 operating system.

Windows Server 2019 refers to the Microsoft Windows Server 2019 operating system.

Microsoft, Windows, Windows Server and Windows Vista are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.