

elite Panaboard software for Mac Revision History (29th/June/2015)

for UB-T880 / UB-T880W / UB-T580 / UB-T580W /

UB-T760 / UB-T761 / UB-T780 / UB-T780BP / UB-T781 / UB-T781W

(c) Panasonic System Networks Co., Ltd. 2007–2015

elite Panaboard software for Mac

Ver.	Changing issue(s) / Fixing problem(s)	Note
2.0.0	1. First Release	
2.1.0	1. (Change Spec) It supported Mac OS X 10.7(Lion).	
2.2.0	1. (Change Spec) It supported UB-T580 / UB-T580W. 2. (Change Spec) It supported UB-T760 / UB-T761 / UB-T780 / UB-T780BP / UB-T781 / UB-T781W. 3. (Change Spec) It supported Mac OS X 10.8(Mountain Lion).	
2.3.0	1. (Change Spec) It supported Mac OS X 10.9(Mavericks). 2. (Change Spec) It finishes the support of Mac OS X 10.5.	
2.4.0	1. (Change Spec) It supported Mac OS X 10.10(Yosemite). 2. (Change Spec) It finishes the support of Mac OS X 10.9.	

*Mac is a trademark of Apple Inc., registered in the U.S. and other countries.

*All other trademarks identified herein are the property of their respective owners.