

Panaboard Software Revision History (28/May/2010)

for UB-5325 / 5825 / 7325 /5315 / 5815 / 5310 / 5320 / 5820 / 7320 /
528P / 628P / 728P / 5328 / 5828 / 5318 / 518B / 618B / 718B

(c) Panasonic System Networks Co., Ltd. 2003-2010.

TWAIN Driver

Ver.	Changing issue(s) / Fixing problem(s)	Note
1.00	1. First Release	
2.00	1. TWAIN Driver name is changed into "Panaboard UB5-7 USB TWAIN Driver" from "Panaboard UB-5 USB TWAIN Driver". 2. Button-Operations in Operation Panel are enabled by Short-cut key. 3. TWAIN Driver judges connection model automatically, displays Operating panel according to the model.	
2.01	1. (Fix) TWAIN Driver cannot close after scanning in KODAK Imaging software in case of connecting by PRICOM (Wireless USB Print Server). It occurs with Windows2000.	
3.00	1. Adding Help button and changing help to HTML Help format.	Version for Windows Vista 32bit
3.10	1. Added Windows Vista 64bit edition as support OS 2. Added Windows 7 32bit & 64bit edition as support OS	Version for Windows 7
3.11	1. (Fix) Image shift might be occurred in scanning by TWAIN driver. *This defect is occurred on only Simplified Chinese version.	

Printer Driver (Windows 98 / Windows Me)

Ver.	Changing issue(s) / Fixing problem(s)	Note
1.00	1. First Release	
1.20	1. "Panaboard-UB7 USB Printer (LT)" and "Panaboard-UB7 USB Printer (A4)" are added for Panaboard 4-screen model (UB-7325/7320) for Windows98/Me.	

Printer Driver (Windows 2000 / Windows XP / Windows Vista / Windows 7)

Ver.	Changing issue(s) / Fixing problem(s)	Note
1.00	1. First Release	
2.00	1. "Panaboard-UB7 USB Printer (LT)" and "Panaboard-UB7 USB Printer (A4)" are added for Panaboard 4-screen model (UB-7325/7320) for Windows2000/XP.	
3.00	1. Changing for Windows Vista 32bit.	Version for Windows Vista 32bit
4.00	1. Added Windows Vista 64bit edition as support OS 2. Added Windows 7 32bit & 64bit edition as support OS	Version for Windows 7

Board Image Capture

Ver.	Changing issue(s) / Fixing problem(s)	Note
3.201	1. First Release	
3.30	1. (Fix) Scan Image cannot be save to root folder.	
3.40	1. Added Windows Vista 64bit edition as support OS 2. Added Windows 7 32bit & 64bit edition as support OS	Version for Windows 7

Software Installer

Ver.	Changing issue(s) / Fixing problem(s)	Note
1.00	1. First Release	
2.00	1. Changing for Windows Vista 32bit.	Version for Windows Vista 32bit
2.14	1. Adding Board Image Capture.	

Notes of Software Installation on Windows Vista / Windows 7

1. If the User Account Control window is displayed, select [Allow].
2. If the Windows Security window is displayed, select [Install this driver software anyway].

When connecting the USB cable to your computer, the wizard window is not displayed in Windows Vista / Windows 7.

* Microsoft, Windows and Windows Vista are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.