## Panasonic Mobile Softphone – List of Tested Devices 1

Tested Model		Tested OS Version	Notes
SAMSUNG	Galaxy S5	Android 5.0	
	Galaxy S7 Edge	Android 7.0	
	Galaxy S8	Android 7.0	
	Galaxy S8+	Android 7.0	
ASUS	ZenFone 5	Android 4.4.2	
	ZenFone 2	Android 5.0	
	ZenFone 3 Max	Android 6.0	Auto-start should be enabled (Settings -> Power management -> Auto-start Manager). Otherwise, incoming calls may not be reached.
LG	G3 Beat	Android 4.4.2	
Google	Nexus 5X	Android 7.1.1	
Motorola	Moto G4 Plus	Android 7.0	
	Moto G5	Android 7.0	

\*1 This list does not guarantee all of the functionalities.

## **Panasonic**

## Mobile Softphone – List of Tested Devices 4

Tested Model		Tested OS Version	Notes
HUAWEI *2	Y6	Android 5.1.1	
	P9 lite	Android 7.0	
	Ascend Mate7	Android 6.0	"Push" should be disabled regardless of PBX models. Otherwise incoming calls will not reached.
	MediaPad T2	Android 5.1.1	
ZTE	Blade V7lite	Android 6.0	

<sup>\*1</sup> This list does not guarantee all of the functionalities.

<sup>\*2</sup> Any devices which are running with Android6 should disable "Push" regardless of PBX models.

Otherwise, incoming calls will not be reached.