

Caution when using Web user interface

(KX-UDS/UDT series)

No. 44-002

December 21 , 2012

Ver.1.1

Panasonic Corporation


Abstract about this document

This document describes about caution when using Web user interface.


Revision history

Date	Version	Revision	Firmware version
Sep. 20, 2012	Ver. 1.0	Initial Release	All versions
Dec. 21, 2012	Ver. 1.1	To add the CS ver. screen of the system option of PS.	UDS124CE: 01.202 or later UDS124 : 01.002 or later

1. Caution when using Web user interface




Appendix : How to confirm IP Address of Super Master CS



1. Turn on the PS.
2. Press [Menu] or the [CENTER] navigation key.
3. Select "**Setting Handset**" and then press [OK].
4. Press [NEXT].
5. Select "**Other Option**" and then press [OK].
6. Select "**MasterCSAddress**" and the press [OK].
 - Display the Master CS IP address.

Appendix : How to Open the CS Web port



1. Turn on the PS.
2. Press [Menu] or the [CENTER] navigation key.
3. Select **"Setting Handset"** and then press [OK].
4. Press [NEXT].
5. Select **"System Option"** and then press [OK].
 - You may need to enter a system password to access this menu.
6. Press [NEXT] to display the second screen, select **"Enable CS Web"**, and then press [OK].
7. When the operation is complete, "CS Web Enabled" is displayed.