\*\*\*\*\*\* Release Note for KV-S1065C/S1046C TWAIN Driver \*\*\*\*\* Copyright(C) 2010-2015, Panasonic System Networks Co., Ltd. All rights reserved. \_\_\_\_\_ Version 13.1.0.1 -> 13.2.0.1 Fixed problems 1. The specific applications (Adobe(R), Photoshop(R), Acrobat(R)) show error, when scanning. 2. The bellow functions are not available with some specific application. - Deskew - Automatic Crop - Automatic Image Orientation - Border Removal - Hole Removal - Blank Page Removal 3. Some specific application does not work without driver's UI, after "No Paper Error" occurred. \_\_\_\_\_ Version 12.0.0.0 -> 13.1.0.1 -----1. (Fix) When setting Border Removal to Automatic and Background to Black, an application error occasionally occurs. 2. (Fix) Some minor bugs are fixed. 3. Add "Turkish" to Automatic Image Orientation function. Version 11.0.0.18 -> 12.0.0.0 Fixed problems 4. The scan finishes with error in case of CAP\_XFERCOUNT value over driver setting. 5. The error checking of enumerate parameter of the capabilities have some problems. 6. The specific Java applications looks freeze after scanning with error. 7. The Error occurs in handling the ICAP\_BITDEPTH in specific applications. 8. To reduce the size of the [TWAIN] dialog box.

\_\_\_\_\_\_

Version 10.1 -> 11.0.0.18

-----

- 1. To support the function of Auto Preview and Auto Rescan.
- 2. Dynamic Threshold and Automatic Separation can be set differently in the front and back.

Target production for above 1. or 2.

- 1. Serial number (11 digits): 7th character from the left is "C" or later, such as xxxxxxCxxxx or xxxxxxDxxxx.
- 2. Firmware version: 2.00 or later
- 3. "Border Removal" can be set in more detail(mode, border style and torn paper correction).

"Remove Shadow" is integrated into "Border Removal".

The mode "Automatic" is old "Border Removal".

The mode "Fixed" is old "Removal Shadow".

- 4. To remove "Invert" function.
- 5. To remove "Mirror" function.

Version 10.0 -> 10.1

1. To support the operating system.

Add "Windows® XP 64bit", "Windows Server® 2003", "Windows Server® 2008", "Windows Server® 2012"

2. Can continue when paper jam occurred.

\_\_\_\_\_

Version 9.2-> 10.0

-----

1. To support for 64 bit application.

\_\_\_\_\_

TWAIN Driver Version 9.2 First version for KV-S1065C/46C

-----

Windows® refers to the Microsoft® Windows® operating system.

Windows® XP refers to the Microsoft® Windows® XP operating system.

Windows Server® 2003 refers to the Microsoft® Windows Server® 2003 operating system.

Windows Server® 2008 refers to the Microsoft® Windows Server® 2008 operating system.

Windows Server® 2012 refers to the Microsoft® Windows Server® 2012 operating system.

Microsoft, Windows, Windows Server and Windows Vista are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

Adobe, Photoshop, Acrobat are either registered trademarks or trademarks of Adobe Systems Incorporated in the United States and/or other countries.