

\*\*\*\*\* Release Note for KV-S3105C/S3085 TWAIN Driver for Package\*\*\*\*\*

Copyright(C) 2010-2012, Panasonic System Networks Co., Ltd. All rights reserved.

-----  
File name '\*\_all\_package' includes TWAIN Driver, Device Driver (STI driver), UserUtility and MCD Utility

=====  
TWAIN Driver Version 7.1.0.2  
-----

1.Fix:A scan may be unable to be stopped.  
=====

IDREngine 1.5  
-----

The installer doesn't support Traditional Chinese UI.

User Utility 6.8  
-----

- 1.To Support KV-S1065C/46C
- 2.Traditional Chinese is excepted.
- 3.Korean is supported.
- 4.The folder which outputs a log file is changed.  
"High Speed Scanner" → "Document Scanner"