

***** Release Note for User Utility *****

Copyright(C) 2010-2016, Panasonic System Networks Co., Ltd. All rights reserved.

=====
Version 6.14-> 6.16

1. To support the models below.
KV-S7097, KV-S7077
KV-SL5100, KV-SL5096, KV-SL5095, KV-SL5086, KV-SL5085
2. Added [LCD contrast] function to the maintenance settings dialog box.
The related models are as follows:
KV-S2087

=====
Version 6.13-> 6.14

1. To Support KV-S2087
2. To support the operating system
Add "Windows® 10"
3. To Support Scanning Glass Cleaning Notification function.
The supported firmware is needed.
4. To Support the Adjusting the hopper position function for KV-S5076H / KV-5046H.
The supported firmware is needed.

=====
Version 6.12-> 6.13

1. To Support KV-S1057C / KV-S1027C / KV-SL1066 / KV-SL1056 / KV-SL1055 / KV-SL1036 / KV-SL1035

=====
Version 6.11-> 6.12

1. To Support KV-S2048C / KV-S2028C

=====
Version 6.10-> 6.11

1. To Support KV-S5076H / KV-S5046H
2. The name of "Caution Setting" button is changed.
"Caution Setting"->"Roller Maintenance"

=====
Version 6.8-> 6.10

-
- 1.To Support KV-S1026C / KV-S1015C
 2. A button to access the download page is added.
 3. A button to save a log file for scanner is added.
 4. The part number of Roller Exchange Kit is added to the message for roller replacing.
 5. To support the operating system
Add "Windows® XP 64bit", "Windows Server® 2003", "Windows Server® 2008", "Windows Server® 2012"
- =====

Version 6.6.0.13-> 6.8.0.20

- 1.To Support KV-S1065C/46C
 - 2.Traditional Chinese is excepted.
 - 3.Korean is supported.
 - 4.The folder which outputs a log file is changed.
"High Speed Scanner" -> "Document Scanner"
- =====

Version 6.6.0.12-> 6.6.0.13

1. When using 'KV-S5055C', waiting sensor information is added in "Save Info" .
- =====

Version 6.5-> 6.6

1. To support new model 'KV-S5055C'.
 2. The help file format is changed from 'PDF' to 'HTML'.
- =====

Version 6.4.0.12-> 6.5.0.1

1. The life of New DFP(double feed prevention) roller is changed from 50,000 to 100,000 sheets and the counter is used in common with counter of paper feed roller as one counter.
And the caution message to replace the rollers is displayed at 100,000 sheets.
2. (Fix) Some bugs are fixed

Windows® refers to the Microsoft® Windows® operating system.

Windows® XP refers to the Microsoft® Windows® XP operating system.

Windows Server® 2003 refers to the Microsoft® Windows Server® 2003 operating system.

Windows Server® 2008 refers to the Microsoft® Windows Server® 2008 operating system.

Windows Server® 2012 refers to the Microsoft® Windows Server® 2012 operating system.

Microsoft, Windows, Windows Server and Windows Vista are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.