

Windows Compliance

1. Film Board/Interactive

Update:31/March/2016

Model	Software	Windows® 10 (64bit)	Windows® 10 (32bit)	Windows® 8 Windows® 8.1 (64bit) (except for Windows® RT)	Windows® 8 Windows® 8.1 (32bit) (except for Windows® RT)	Windows® 7 (64bit)	Windows® 7 (32bit)	Windows Vista® (64bit)	Windows Vista® (32bit)	Windows® XP (64bit)	Windows® XP (32bit)
KX-BP800 Series	Interactive Panaboard Software	NO	NO	NO	NO	YES	YES	YES	YES	NO	YES
	Quick Image Navigator	NO	NO	NO	NO	YES	YES	NO	YES	NO	YES
	Panasonic-DMS	NO	NO	NO	NO	NO	NO	NO	YES	NO	YES
	TWAIN Driver	NO	NO	NO	NO	YES	YES	YES	YES	NO	YES
	Printer Driver	NO	NO	NO	NO	YES	YES	YES	YES	NO	YES
UB-5315(UB-5328) UB-5815(UB-5828) UB-5310(UB-5318) UB-5325(UB-538P) UB-5825(UB-628P) UB-7325(UB-728P) UB-5320(UB-518B) UB-5820(UB-618B) UB-7320(UB-718B)	Quick Image Navigator	YES	YES	YES	YES	YES	YES	NO	YES	NO	YES
	Panasonic-DMS	NO	NO	NO	NO	NO	NO	NO	YES	NO	YES
	TWAIN Driver	YES	YES	YES	YES	YES	YES	YES	YES	NO	YES
	Printer Driver	YES	YES	YES	YES	YES	YES	YES	YES	NO	YES
UB-8325	Interactive Panaboard Software	YES (*1)	YES (*1)	YES	YES	YES	YES	YES	YES	NO	YES
	Quick Image Navigator	YES	YES	YES	YES	YES	YES	NO	YES	NO	YES
	Panasonic-DMS	NO	NO	NO	NO	NO	NO	NO	YES	NO	YES
	TWAIN Driver	YES	YES	YES	YES	YES	YES	YES	YES	NO	YES
	Printer Driver	YES	YES	YES	YES	YES	YES	YES	YES	NO	YES
UB-2815C(UB-2818C) UB-2315C(UB-2318C)	Quick Image Navigator	NO	NO	NO	NO	YES	YES	NO	YES	NO	YES
	Panasonic-DMS	NO	NO	NO	NO	NO	NO	NO	YES	NO	YES
	TWAIN Driver, Board Image Capture	NO	NO	NO	NO	NO	YES	NO	YES	NO	YES
	Printer Driver	NO	NO	NO	NO	NO	YES	NO	YES	NO	YES
UB-5338C UB-5838C UB-5335 UB-5835 UB-5365 UB-5865	No software or device drivers required	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES
	Panaboard Overlayer	YES	YES	YES	YES	YES (SP1 or later)	YES (SP1 or later)	YES (SP2 or later)	YES (SP2 or later)	NO	YES (SP3 or later)

YES:Checked

NO:Not checked or Not work

(*1) If you choose a Windows keyboard on the screen keyboard, it will not be able to input characters using an electronic pen.

Note

You must select [Restart] instead of [Shut down] to restart Windows 8 after installation.

Microsoft, Windows and Windows Vista are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.

2. elite Panaboard

Model	Software	Windows® 10 (64bit)	Windows® 10 (32bit)	Windows® 8 (64bit) Windows® 8.1 (64bit) (except for Windows® RT)	Windows® 8 (32bit) Windows® 8.1 (32bit) (except for Windows® RT)	Windows® 7 (64bit)	Windows® 7 (32bit)	Windows Vista® (64bit)	Windows Vista® (32bit)	Windows® XP (64bit)	Windows® XP (32bit)
UB-T580 UB-T580W	elite Panaboard software	YES	YES	YES	YES	YES*	YES*	YES (SP2 or later)	YES (SP2 or later)	NO	YES (SP3 or later)
UB-T880 UB-T880W	elite Panaboard book	YES	YES	YES	YES	YES*	YES*	YES (SP2 or later)	YES (SP2 or later)	NO	YES (SP3 or later)
UB-T780 UB-T781	elite Panaboard software	NO	NO	NO	NO	YES	YES	YES	YES	NO	YES (SP2 or later)
UB-T781W UB-T761	elite Panaboard book	NO	NO	NO	NO	YES	YES	YES	YES	NO	YES (SP2 or later)

YES:Checked

NO:Not checked or Not work

* except for Starter, Home Basic Edition

	Windows® 10 (64bit)	Windows® 10 (32bit)	Windows® 8 (64bit) Windows® 8.1 (64bit) (except for Windows® RT)	Windows® 8 (32bit) Windows® 8.1 (32bit) (except for Windows® RT)	Windows® 7 (64bit)	Windows® 7 (32bit)	Windows Vista® (64bit)	Windows Vista® (32bit)	Windows® XP (64bit)	Windows® XP (32bit)
UB-T880 Series, UB-T781 Series Option UE-608040 (Wireless Kit)	NO	NO	NO	NO	YES	YES	YES	YES	NO	YES (SP2 or later)
UB-T780 Series, UB-T781 Series Option UE-608050 (Install Free Kit)	NO	NO	NO	NO	YES	YES	YES	YES	NO	YES (SP2 or later)

YES:Checked

NO:Not checked or Not work

Note

You must select [Restart] instead of [Shut down] to restart Windows 8 after installation.

Microsoft, Windows and Windows Vista are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.