

***** Release Note for Multicolor Drop Out Utility*****

(c) Panasonic Corporation 2010-2021

=====
Version 6.11 -> 6.12

-
1. To support the model below.
KV-S6120, KV-S6110, KV-S6100

=====
Version 6.9 -> 6.11

-
1. To support the model below.
KV-S5078Y, KV-S5058,
KV-SL5100 MK2 / KV-SL5096 MK2 / KV-SL5095 MK2 / KV-SL5086 MK2 / KV-SL5085 MK2

=====
Version 6.9 -> 6.10

-
1. Only version is changed.

=====
Version 6.8 -> 6.9

-
1. To support the models below.
KV-SL1077 MK2

=====
Version 6.7 -> 6.8

-
1. To support the models below.
KV-SL1066 MK2, KV-SL1056 MK2, KV-SL1055 MK2, KV-SL1036 MK2, KV-SL1035 MK2
 2. To support the operating system.
Add "Windows Server 2019"

=====
Version 6.5 -> 6.7

-
1. Only version is changed.

=====

Version 6.4 -> 6.5

- 1. To support the models below.
KV-N1058X, KV-N1028X, KV-N1058Y, KV-N1028Y

=====

Version 6.3 -> 6.4

- 1. To support the models below.
KV-S1037X

=====

Version 6.1 -> 6.3

- 1. To support the models below.
KV-S1058Y, KV-S1057C MK2, KV-S1028Y, KV-S1027C MK2
KV-S1038, KV-S1037, KV-S1026C MK2

=====

Version 6.0 -> 6.1

- 1. To support the models below.
KV-SL3066, KV-SL3056, KV-SL3055, KV-SL3036, KV-SL3035
- 2. To support the operating system.
Add "Windows Server 2016"

=====

Version 5.4 -> 6.0

- 1. To support the models below.
KV-S8150, KV-S8147, KV-S8130, KV-S8127, KV-S8120

=====

Version 5.3 -> 5.4

- 1. To support the models below.
KV-S7097, KV-S7077
KV-SL5100, KV-SL5096, KV-SL5095, KV-SL5086, KV-SL5085

=====

Version 5.2 -> 5.3

1. To support the models below.

KV-S2087

2. To support the operating system.

Add "Windows 10"

=====

Version 5.1 -> 5.2

1. To support the models below.

KV-S1057C / KV-S1027C / KV-SL1066 / KV-SL1056 / KV-SL1055 / KV-SL1036 / KV-SL1035

=====

Version 5.0 -> 5.1

1. To support the models below.

KV-S5076H / KV-S5046H

=====

Version 4.6 -> 5.0

1. To support the models below.

KV-S1026C / KV-S1015C

2. To support the operating system.

Add "Windows XP 64bit", "Windows Server 2003", "Windows Server 2008", "Windows Server 2012"

=====

Version 4.5 -> 4.6

1. To support the models below.

KV-S1065C/46C

2. Traditional Chinese is excepted.

3. Korean is supported.

4. The folder which outputs a setting file is changed.

"High Speed Scanner" -> "Document Scanner"

=====

Version 4.5 -> 4.6

1. To support the models below.

KV-S5055C

2. The help file format is changed from 'PDF' to 'HTML'.

Windows refers to the Microsoft Windows operating system.

Windows XP refers to the Microsoft Windows XP operating system.

Windows Vista refers to the Microsoft Windows Vista operating system.

Windows 7 refers to the Microsoft Windows 7 operating system.

Windows 8 refers to the Microsoft Windows 8 operating system.

Windows 10 refers to the Microsoft Windows 10 operating system.

Windows Server 2003 refers to the Microsoft Windows Server 2003 operating system.

Windows Server 2008 refers to the Microsoft Windows Server 2008 operating system.

Windows Server 2012 refers to the Microsoft Windows Server 2012 operating system.

Windows Server 2016 refers to the Microsoft Windows Server 2016 operating system.

Windows Server 2019 refers to the Microsoft Windows Server 2019 operating system.

Microsoft, Windows, Windows Server and Windows Vista are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries.