\*\*\*\*\* Release Note for KV-S3065C TWAIN Driver for Package \*\*\*\*\*

Copyright(C) 2010- 2012, Panasonic System Networks Co., Ltd. All rights reserved.

\_\_\_\_\_

File name '\*\_ all\_package' includes TWAIN Driver, Device Driver (STI driver), UserUtility and MCD Utility

TWAIN Driver Version 9.2

-----

1. To support the distance between documents for Multi-Crop setting.

2. Fix: A scan may be unable to be stopped.

**IDREngine 1.5** 

-----

The installer doesn't support Traditional Chinese UI.

User Utility 6.8

\_\_\_\_\_

1.To Support KV-S1065C/46C

2. Traditional Chinese is excepted.

3.Korean is supported.

4. The folder which outputs a log file is changed.

"High Speed Scanner" → "Document Scanner"