****** Release Note for Firmware of KV-S5055C *****
Copyright(C) 2013-2014, Panasonic System Networks Co., Ltd. All rights reserved.
Version 1.21 -> 1.22
Improved Document Detect Sensor adjustment process.
Version 1.20 -> 1.21
Improved Double Feed Detect Sensor check process.
Improvement of imprinter detection.
======================================
Fixed problems 1. Background color on startup is not recognized properly. 2. Other problem
Version 1.03 -> 1.04
Change in production line of factory
======================================

1.Change of maximum top / bottom margin 10mm -> 15mm